


## HVP 125

### High voltage meter

89

Description	P/N
HVP 125	R9K VXM 030

To precisely measure the high voltage at the tip of the applicator. The meter comes with a ground connection that **MUST** be connected to ground prior to starting. To get a measurement, place the spherical end of the probe in contact with the electrode (of the gun), or with the bellcup . Press the thumb switch: direct reading from the meter display.

 To use only in no explosive atmospheres.



### Handgun protection cover

Description	P/N
Set of 10 covers	1 202 466#



### Tube of dielectric grease

Description	P/N
White vaseline (100cc tube)	H1G MIN 017 <sup>(1)</sup>
Red dielectric grease (50 gr.)	H1G SYN 037 <sup>(2)</sup>

(1): recommended for the o-rings in contact with rinsing materials (solvent)

(2): dielectric grease, used for high voltage input plug

